## Department of Transportation—Federal Aviation Administration

## Supplemental Type Certificate

Number SA3889NM

This certificate, issued to

**New Century Designs** 11720 Garfield Street Thornton, Colorado 80233

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product—Type Certificate Number:

A10CE

Learjet

Model:

25B, 35, and 35A

Description of the Type Design Change:

Installation of emergency medical system in accordance with Drawing List RDL-01, Rev. C, dated August 4, 1995 for Learjet Model 25B aircraft, and Drawing List ARTD-DL-01, Rev. Original, dated September 1, 1999, for Learjet Model 35 Series aircraft, or later FAA approved revision.

## Limitations and Conditions:

- FAA Approved Aircraft Flight Manual Supplement, dated February 9, 1988, or later approved revision is
- 2. Compatibility of this design change with previously approved modifications must be determined by installer.
- A copy of this Certificate and the Instructions for Continued Airworthiness as addressed in document ARTD-MMS-01 entitled, "Maintenance Manual Supplement", Revision Original, FAA accepted December 13, 1999, or later accepted revision is required and must be maintained as a part of the permanent records for each
- 4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

August 14, 1987

Date reissued:

Date of issuance:

February 9, 1988

Date amended: 6/22/92; 7/10/92; 8/3/92; October 5, 2000

By direction of the Administrator

Carrie K. Beach (Signature) Acting Manager

Northwest Mountain Region

Denver Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.